

[illegible][illegible][illegible]

- [illegible]

[illegible][illegible][illegible]

- 202108110150
08/11/2021 03:43 PM Page 2 of 2
- TREE TABLE**

TREE NO.	DESCRIPTION
T-1	10' FIR
T-2	10' FIR
T-3	6' FIR
T-4	6' FIR
T-5	6' FIR
T-6	6' FIR
T-7	24' CEDAR
T-8	24' CEDAR
T-9	10' FIR
T-10	24' FIR CLUSTER (4-6)
T-11	24' CEDAR
T-12	24' CEDAR
T-13	12' FIR
T-14	12' FIR
T-15	12' FIR
T-16	12' FIR
T-17	12' FIR
T-18	12' FIR
T-19	12' FIR
T-20	12' FIR
T-21	12' FIR
T-22	12' FIR
T-23	12' FIR
T-24	12' FIR
T-25	12' FIR

EXISTING CORNERS FOUND

LINE NO.	DESCRIPTION
1	1/2" REBARCAP TIEBARS SET IN CONCRETE
2	0.1' N & 0.1' M OF CALCD POSITION
3	1/2" REBARCAP TIEBARS SET IN CONCRETE
4	0.6' N OF CALCD POSITION
5	1/2" REBARCAP TIEBARS SET IN CONCRETE
6	0.3' N & 0.1' E OF CALCD POSITION
7	1/2" REBARCAP TIEBARS SET IN CONCRETE
8	0.1' N & 0.2' E OF CALCD POSITION
9	1/2" REBARCAP TIEBARS SET IN CONCRETE
10	0.6' N OF CALCD POSITION
11	1/2" REBARCAP TIEBARS SET IN CONCRETE
12	0.3' N & 0.1' M OF CALCD POSITION

LINE TABLE

LINE NO.	BEARING	DISTANCE
L1	N 0° 15' 30" E	75.20
L2	N 89° 59' 59" E	102.50
L3	N 89° 59' 59" E	61.54
L4	N 0° 45' 11" E	80.03
L5	S 89° 45' 21" W	30.02

CURVE TABLE

LINE NO.	BEARING	DISTANCE
C1	N 0° 15' 30" E	232.15
C2	N 89° 59' 59" E	46.93
C3	S 2° 10' 04" E	22.47
C4	S 89° 59' 59" E	74.14
C5	N 89° 59' 59" E	150.00
C6	S 1° 13' 41" E	86.01
C7	S 89° 45' 21" W	72.24
C8	N 0° 15' 30" E	102.50
C9	N 89° 59' 59" E	102.50
C10	N 89° 59' 59" E	61.54
C11	N 0° 45' 11" E	80.03
C12	S 89° 45' 21" W	30.02

OCCUPATIONAL INDICATORS

LINE NO.	DESCRIPTION
1	FENCE CORNER IS 3' 6" EAST
2	FENCE CORNER IS 3' 6" EAST
3	FENCE CORNER IS 3' 6" EAST
4	FENCE CORNER IS 3' 6" EAST
5	FENCE CORNER IS 3' 6" EAST
6	FENCE CORNER IS 3' 6" EAST
7	FENCE CORNER IS 3' 6" EAST
8	FENCE CORNER IS 3' 6" EAST
9	FENCE CORNER IS 3' 6" EAST
10	FENCE CORNER IS 3' 6" EAST
11	FENCE CORNER IS 3' 6" EAST
12	FENCE CORNER IS 3' 6" EAST

NOTE: FOUND TIEBARS CAPED REBAR, WHICH ARE IN CONCRETE, WERE ORIGINALLY SET PER RE-PLAT OF A PORTION OF FIRREST ESTATES CONDOMINIUMS, PHASE I. RECORDED UNDER AF NO. 42090100. IT APPEARS THAT THE CORNERS WERE DISTURBED WHEN RESET IN CONCRETE. THE ORIGINAL CORNERS WERE NOT SET IN CONCRETE.

202108110150
08/11/2021 03:43 PM Page 2 of 2

TREE TABLE

TREE NO.	DESCRIPTION
T-1	10' FIR
T-2	10' FIR
T-3	6' FIR
T-4	6' FIR
T-5	6' FIR
T-6	6' FIR
T-7	24' CEDAR
T-8	24' CEDAR
T-9	10' FIR
T-10	24' FIR CLUSTER (4-6)
T-11	24' CEDAR
T-12	24' CEDAR
T-13	12' FIR
T-14	12' FIR
T-15	12' FIR
T-16	12' FIR
T-17	12' FIR
T-18	12' FIR
T-19	12' FIR
T-20	12' FIR
T-21	12' FIR
T-22	12' FIR
T-23	12' FIR
T-24	12' FIR
T-25	12' FIR

EXISTING CORNERS FOUND

LINE NO.	DESCRIPTION
1	1/2" REBARCAP TIEBARS SET IN CONCRETE
2	0.1' N & 0.1' M OF CALCD POSITION
3	1/2" REBARCAP TIEBARS SET IN CONCRETE
4	0.6' N OF CALCD POSITION
5	1/2" REBARCAP TIEBARS SET IN CONCRETE
6	0.3' N & 0.1' E OF CALCD POSITION
7	1/2" REBARCAP TIEBARS SET IN CONCRETE
8	0.1' N & 0.2' E OF CALCD POSITION
9	1/2" REBARCAP TIEBARS SET IN CONCRETE
10	0.6' N OF CALCD POSITION
11	1/2" REBARCAP TIEBARS SET IN CONCRETE
12	0.3' N & 0.1' M OF CALCD POSITION

LINE TABLE

LINE NO.	BEARING	DISTANCE
L1	N 0° 15' 30" E	75.20
L2	N 89° 00' 00" E	100.00
L3	N 89° 20' 23" E	61.54
L4	N 0° 40' 51" E	80.03
L5	S 89° 45' 21" W	30.02

CURVE TABLE

LINE NO.	BEARING	DISTANCE
C1	N 0° 15' 30" E	232.15
C2	N 89° 00' 00" E	111.61
C3	N 89° 20' 23" E	46.93
C4	N 0° 40' 51" E	22.47
C5	N 0° 15' 30" E	74.14
C6	N 89° 00' 00" E	100.00
C7	N 89° 20' 23" E	61.54
C8	N 0° 40' 51" E	80.03
C9	N 0° 15' 30" E	75.20
C10	N 89° 00' 00" E	100.00
C11	N 89° 20' 23" E	61.54
C12	N 0° 40' 51" E	80.03

OCCUPATIONAL INDICATORS

LINE NO.	DESCRIPTION
1	FENCE CORNER IS 3' 6" EAST
2	FENCE CORNER IS 3' 6" EAST
3	FENCE CORNER IS 3' 6" EAST
4	FENCE CORNER IS 3' 6" EAST
5	FENCE CORNER IS 3' 6" EAST
6	FENCE CORNER IS 3' 6" EAST
7	FENCE CORNER IS 3' 6" EAST
8	FENCE CORNER IS 3' 6" EAST
9	FENCE CORNER IS 3' 6" EAST
10	FENCE CORNER IS 3' 6" EAST
11	FENCE CORNER IS 3' 6" EAST
12	FENCE CORNER IS 3' 6" EAST

NOTE: FOUND TIEBARS CAPED REBAR, WHICH ARE IN CONCRETE, WERE ORIGINALLY SET PER RE-PLAT OF A PORTION OF FIRREST ESTATES CONDOMINIUMS, PHASE I. RECORDED UNDER AF NO. 42090100. IT APPEARS THAT THE CORNERS WERE DISTURBED WHEN RESET IN CONCRETE. THE ORIGINAL CORNERS WERE NOT SET IN CONCRETE.

[illegible][illegible][illegible][illegible][illegible]