Burlington-Edison School District #100 927 East Fairhaven Avenue Burlington, WA 98233 360-757-3311

School District Profile:

List of Properties Owned	Addresses	\$ Estimated Value
See attached sheet for detailed property listing.		
	Building Value	\$70254060
	Equipment Value	\$7654496
	Total	\$ 77908556.

Hazards and Mitigation Strategies:

Hazard & Effect	Mitigation & Preparedness (Protection devices, safeguards, & procedures to reduce effect of the hazard)	Response (Immediate actions to function at a minimal acceptable level)	Recovery (Resources required to restore function or longer term recovery)
Earthquake	Emergency generators needed at Bay View Elementary, West View Elementary and Allen Elementary for emergency back-up power. Lead Department: Auxiliary Services Funding Source: Grant Funding Time-line: Short Term – less than three (3) years Regular drills performed and recorded at all schools. Earthquake insurance coverage in place.	Conduct comprehensive facility survey. Itemize damage, structural, nonstructural, equipment, utility and communications systems. Take photos for records and damage evaluation.	Emergency generators needed at Bay View Elementary, West View Elementary and Allen Elementary for emergency back-up power. Prioritize and schedule both temporary and permanent repairs.

Hazard & Effect	Mitigation & Preparedness (Protection devices, safeguards, & procedures to reduce effect of the hazard)	Response (Immediate actions to function at a minimal acceptable level)	Recovery (Resources required to restore function or longer term recovery)
	All schools have a limited food supply for students and staff.		
Fire	Fire insurance coverage in place. Comply with Fire Codes and regulations per annual inspections. Automatic sprinkler systems. Regular drills performed and recorded at all schools.	Close off damaged section for safety. Evaluate damage with insurance representative.	Relocate employees and salvaged equipment. Prioritize and schedule both temporary and permanent repairs.
Severe Wind	All schools have a limited food supply for students and staff. Emergency generators needed at Bay View Elementary, West View Elementary and Allen Elementary for emergency back-up power. Lead Department: Auxiliary Services Funding Source: Grant Funding Time-line: Short Term – less than three (3) years	Tour facilities to assess damage. Notify insurance representative. Update employees on conditions.	Prioritize and schedule both temporary and permanent repairs. Emergency generators needed at Bay View Elementary, West View Elementary and Allen Elementary for emergency back-up power.

Hazard & Effect	Mitigation & Preparedness (Protection devices, safeguards, & procedures to reduce effect of the hazard)	Response (Immediate actions to function at a minimal acceptable level)	Recovery (Resources required to restore function or longer term recovery)
Snow Storm	All schools have a limited food supply for students and staff. School buses have chains available. Emergency routes have been established.	Snow removal from walks and parking lots. Tour facility to assess damage. Update employees on conditions.	Prioritize and schedule both temporary and permanent repairs.
Volcanic Activity (Mt. Baker)	Procedure in place to protect ventilation intakes. All schools have a limited food supply for students and staff.	Activate plans for protection of ventilation system	Prioritize and schedule both temporary and permanent repairs.

PROPOSED MITIGATION MEASURE:

Provide for the purchase and installation of emergency generators (as indicated in the document above) at the Bay View Elementary School, the West View Elementary School, and the Allen Elementary School.

Lead Department: Auxiliary Services Funding Source: Grant Funding

Time-line: Short Term (less than 3 years from receiving funding)