

TANK PUMPING REPORT

Site Name:

Location: 12637 PULVER ROAD MH #1
BURLINGTON

Tax ID: P23643

Use: Residential, Manufactured Home

Service Company:

Johnny's Septic Service, Incorporated

P.O.Box 1128
Burlington, WA 98233
360-757-0550

Serviced: 05/21/2024 by: Shawn Graham

Submitted 07/22/2024 by: Jessica Burrow

Dump Location: La Conner Waste Water Treatment Plant

Jurisdiction ID: 62235

COMMENTS

System flooded upon arrival.
Homeowner to reach out to local designer.

TANK: Septic Tank - 1 Compartment

Tank Pumped:	YES	
Tank Size (Gallons)(Number only, no text):	750	
Effluent level within operational limits (if NO explain in comments):	NO	Deficient
Total Gallons pumped from tank (Number only, no text):	800	
Effluent returning back into tank after pumping:	NO	
Tank depth below grade (inches):	0	
Access Risers installed to grade (N/A if not present):	NO	
Tank Construction Material:	Concrete	
Tank Condition Good:	NO	Deficient
Baffles in good condition (N/A if not present):	NO	Deficient
Effluent screen cleaned (N/A if not present):	N/A	
Effluent surfacing around site components (N/A if not checked):	NO	
Tank abandoned after pumping:	NO	
Were repairs made to the Tank or Tank Components? (if YES explain in comments):	NO	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	3	

This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.