

TANK PUMPING REPORT

Site Name:

Location: 12637 PULVER ROAD MH #1
BURLINGTON

Tax ID: P23643

Use: Residential, Manufactured Home

Service Company:

Johnny's Septic Service, Incorporated

P.O.Box 1128
Burlington, WA 98233
360-757-0550

Serviced: 08/20/2024 by: Shawn Graham

Submitted 08/21/2024 by: Jessica Burrow

Dump Location: La Conner Waste Water Treatment Plant

Jurisdiction ID: 62235

COMMENTS

System flooded upon arrival.
Homeowner to contact local designer.
Tank appears to be bottomless cess pit.
Cracks & root infiltration in sidewall of concrete tank of top of pit.
There are 5-6 inlets into tank, none of which have baffles.
4-6 structures & multiple RVs appear to be connected to pit.
Pit does not appear to be draining properly.
Johnny's Septic does not warrant this system.

TANK: Septic Tank - 1 Compartment

Tank Pumped:	YES	
Tank Size (Gallons)(Number only, no text):	750	
Effluent level within operational limits (if NO explain in comments):	NO	Deficient
Total Gallons pumped from tank (Number only, no text):	830	
Effluent returning back into tank after pumping:	YES	Deficient
Tank depth below grade (inches):	0	
Access Risers installed to grade (N/A if not present):	N/A	
Tank Construction Material:	Concrete	
Tank Condition Good:	NO	Deficient
Baffles in good condition (N/A if not present):	N/A	
Effluent screen cleaned (N/A if not present):	N/A	
Effluent surfacing around site components (N/A if not checked):	YES	Deficient
Tank abandoned after pumping:	NO	
Were repairs made to the Tank or Tank Components? (if YES explain in comments):	NO	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	3	

This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.