

- This is only a list those records that are within the map series extents -

SITEID	REACH	LOCATION	EDGETYPE	LEVEE	MODTYPE	PURPOSE	OLD_NEW	YR_PLACED	DOM_SIZE	SUB_DOM_SI	RIP_TYPE	COMMENTS	RIPBUFF	LENGTH_M
20-19	Sk040	RB	non-hardened bank	none							mature		> 60 m	893.38399591300
20-20	Sk040	RB	bar	none							mature		> 60 m	195.38076428700
20-21	Sk040	RB	non-hardened bank	none							mature		> 60 m	374.59718658400
20-22	Sk040	RB	bar	none							mature		> 60 m	34.74773371250
20-23	Sk040	RB	non-hardened bank	none							mature		> 60 m	341.07577020500
20-24	Sk040	RB	bar	none							mature		> 60 m	53.33879125580
20-25	Sk040	RB	hardened bank	none	riprap/bridge pier		old	pre 1990	>2'		mature	bridge pier at top of section	> 60 m	29.26064984040
20-4	Sk040	LB	hardened bank	none	riprap		old	post 1990	>2'		mature		5 to 20 m	1537.13655188000
20-5	Sk040	LB	hardened bank	none	riprap/rubble		new	pre 1990	>2'		mature	rubble is cement slabs	5 to 20 m	192.63788157400
20-6	Sk040	LB	hardened bank	none	riprap/rubble		old	post 1990	>2'		mature		> 60 m	178.91611640100
20-7	Sk040	LB	hardened bank	none	riprap/rubble		old	post 1990	>2'		mature	bridge pier at top of section	5 to 20 m	360.27250223900
SK050-1	Skdelta	RB	hardened bank	none	riprap/rubble/groins	protects bridge, cabins, Sedro Woolley	old/new	pre 1990/post 1990	> 2'	sand	mature	3 old groins, cement slabs & blocks & logs cabled together, old appliances, new riprap at Steelhead Club ramp, grass/cotton/shrub/alder around houses and cabin	5 to 40 m	1868.37251738000
SK050-2	Skdelta	LB	hardened bank	none	riprap	protects fishing camps (?)	old	pre 1990	> 2'	sand	mature	located by Tarheel hole, alders(12-16")	20 to 40 m	244.44905107600
SK060A-1	SK060A	RB	hardened bank	adjacent	riprap	protects farmland	old	pre 1990	> 2'	silt/sand	mature	located in Skiyou Sl, RB of slough has riprap, LB does not	< 5 m	555.92082814800
SK060A-10	SK060A	RB	hardened bank	none	riprap	protects farmland/woods	old	pre 1990	> 2'		immature		> 60 m	295.45858146600
SK060A-11	SK060A	RB	hardened bank	none	riprap	protects farmland	new	post 1990	> 2'		immature	riprap is at point only	5 to 20 m	21.68808492390
SK060A-12	SK060A	RB	hardened bank	none	riprap/rubble	protects farmland	old/new	pre 1990/post 1990	> 2'		immature	debris incl car bodies & cement slabs, new riprap at dwnstrm edge at pt, old riprap & pilings w/ LOD along upper section, culvert w/ flapper valve	< 5 m	785.52358799900
SK060A-13	SK060A	LB	hardened bank	none	riprap	protects farmland	old	pre 1990	> 2'	6"	mature	along Casbab Sl.	5 to 20 m	274.24088502800
SK060A-14	SK060A	LB	hardened bank	none	riprap	protects farmland	old	pre 1990	> 2'		open	80m up from the lower end - the riprap is breached/washed out, new LOD jam has formed along the bank at washout	none	369.69451396500
SK060A-15	SK060A	RB	hardened bank	none	riprap/groin	protects town of Lyman	old/new	pre 1990/post 1990	> 2'	1-2'	open	5 groins in the new section at lower end, top end is old riprap, vegetation is only along old riprap	none	612.46180421900
SK060A-16	SK060A	RB	hardened bank	none	rubble	protects field	old	pre 1990			immature	debris is cement slabs, section is 50' long	5 to 20 m	54.43208191430
SK060A-17	SK060A	RB	hardened bank	none	riprap	protects road and field	new	post 1990	> 2'		immature	vegetation is on top of bank only, small alders are backset from the bank	5 to 20 m	1169.04172934000
SK060A-18	SK060A	RB	hardened bank	none	riprap	protects private land	old	pre 1990	> 2'	sand	mature	located behind island/bar area, old side channel along road w/ lots of LOD but no riprap seen along the side channel, only along edge of mainstem	> 60 m	156.89497273400
SK060A-19	SK060A	RB	hardened bank	none	riprap/rubble	protects Sedro Woolley	old	pre 1990	> 2'	sand	mature	rubble incl cement slabs, blocks & logs cabled together, old appliances, culvert enters riv just below mouth of Hansen Cr, grass/cotton/shrub/alder	5 to 40 m	1806.02657978000
SK060A-2	SK060A	LB	hardened bank	none	riprap	protects So. Skagit Hwy	old	pre 1990	> 2'	6-8'	mature	lower end bedrock w/ slump, riprap continues upriver into side channel along hwy which is 80m inland from river's edge, alders(16-20")/grasses and a few evergr	> 60 m	867.41924380400
SK060A-20	SK060A	LB	hardened bank	none	riprap	protects So. Skagit Hwy	old	pre 1990	> 2'	sand	mature	starts above the houses and continues upriver into side channel along hwy, there is a section of bedrock at the pipeline crossing, grasses/alders(to 14")	> 60 m	1294.88207528000
SK060A-3	SK060A	LB	hardened bank	none	riprap	protects So. Skagit Hwy	old	pre 1990	> 2'	6-8'	mature	alders(16-20")/grasses and a few evergreens	> 60 m	425.74679871300
SK060A-4	SK060A	LB	hardened bank	none	riprap	unknown	old	pre 1990	> 2'	6-8'	mature	riprap is at the point, downstream side of small side channel	> 60 m	41.32547114780
SK060A-5	SK060A	RB	hardened bank	none	riprap	protects wooded land	new	post 1990	> 2'	1'	mature	deflector?, upstream side is eroded away so that the riprap rock extends 40m into the river, there's a sandy high bank at top edge of the piece of riprap	> 60 m	37.22677892770
SK060A-6	SK060A	RB	hardened bank	none	riprap	protects a farm road that connects 2 pastures	new	post 1990	> 2'		mature	located at mouth of sm slough, at road crossing is 3' dia cement culvert, at this flow culvert is 4' above the water level of river, house is located on RB sid	> 60 m	54.87740138180
SK060A-7	SK060A	RB	hardened bank	none	riprap	protects farmland	old/new	pre 1990/post 1990	> 2'		immature	new riprap located at downstream corner, goes to old riprap then very old riprap with heavy veg, only a few pieces of rock exposed along this slough	> 60 m	413.04243744500
SK060A-8	SK060A	LB	hardened bank	none	riprap	protects houses and road	old/new	pre 1990/post 1990	> 2'	0.5-1'	immature		5 to 20 m	788.59627323600
SK060A-9	SK060A	RB	hardened bank	none	riprap	protects farmland	old/new	pre 1990/post 1990	> 2'	1'	immature	evidence of a recent wash-out, seen by slump, upstream edge of riparian is only 5m wide, downstream edge is 20m	5 to 20 m	316.38212040800
SK060B-1	SK060B	RB	hardened bank	none	riprap/debris	protects farmland	old	pre 1990	> 2'	sand	open		none	219.73391760900
SK060B-10	SK060B	RB	hardened bank	none	pilings/jetty	unknown	old	pre 1990			mature	18 inch dia pilings, acts as flow deflector	> 60 m	88.07869512700
SK060B-11	SK060B	RB	hardened bank	none	riprap	protects road	old	pre 1990	< 2'		immature	starts at slough, interspersed w/ areas of bedrock, lower protects bank	5 to 20 m	272.47476800800
SK060B-2	SK060B	RB	hardened bank	none	riprap/debris	protects cabins	old/new	pre 1990/post 1990	> 2'		mature	new riprap is in 4 sections, debris = tires, slabs & cinder blocks, these are not continuous, riparian stand is only at upstream end	20 to 40 m	411.22402112300
SK060B-3	SK060B	LB	hardened bank	none	riprap	protects house	old	pre 1990	> 2'		mature	this is only a 50-75' section of riprap, riparian zone is scattered amongst the houses	> 60 m	62.96204884550
SK060B-4	SK060B	RB	hardened bank	none	riprap/debris	protects cabins	old	pre 1990	> 2'	sand	mature	debris = cement slabs at the upper corner	> 60 m	69.81522307200
SK060B-5	SK060B	LB	hardened bank	none	riprap	protects summer trailer spot along So. Skagit Hwy	old	pre 1990	< 2'		mature	two step terrace of small rocks	> 60 m	50.17178988750
SK060B-6	SK060B	LB	hardened bank	none	riprap	protects So. Skagit Hwy	old/new	pre 1990/post 1990	> 2'	sand	mature	old riprap among high bank bedrock, new riprap covered w/ moss & sm alders along upper end below partial road slump & @ connection of old Cumberland Cr chan	> 60 m	868.86117811700
SK060B-7	SK060B	RB	hardened bank	adjacent	riprap/groin	protects farmland & road	old/new	pre 1990/post 1990	> 2'	1'	immature	2 step tier (riprap adj to levee) w/ new riprap along camp area, 3 groins dwnstrm end, ends upstrm at Muddy Cr, levee mostly adj except at mid corner = 20 to 4	< 5 m	1950.71822301000
SK060B-8	SK060B	LB	hardened bank	none	riprap	protects So. Skagit Hwy	old	pre 1990	> 2'	1-2'	mature	riprap to the outlet of old steelhead acclimation pond at Black Sl	> 60 m	1096.6844038000
SK060B-9	SK060B	RB	hardened bank	none	riprap	protects houses from Hamilton boat ramp to Alder Creek	old	pre 1990	> 2'		mature	protects houses and cabins from Hamilton boat ramp to Alder Creek, but washed out just above boat ramp, riparian zone has lots of houses in it	20 to 40 m	1925.75747120000
SK070A-1	SK070A	RB	hardened bank	none	riprap	protects road	old	pre 1990	< 2'		immature	starts at slough, interspersed w/ areas of bedrock to cable crossing, 2 step riprap, lower protects bank, upper protects houses, grass/bb/alder/cedar	5 to 20 m	954.51153335400
SK070B-1	SK070B	LB	hardened bank	none	riprap	protects So. Skagit Hwy	old	pre 1990	> 2'	rubble/sand	mature		> 60 m	652.13956623500
SK070B-2	SK070B	LB	hardened bank	none	riprap	protects So. Skagit Hwy	old/new	pre 1990/post 1990	> 2'		mature	New, installed in 1996	< 5 m	686.03599678900
SK070B-3	SK070B	RB	hardened bank	none	riprap	protects Birdview boat ramp	old	pre 1990	> 2'		mature		20 to 40 m	40.08323833120
SK070B-4	SK070B	RB	hardened bank	none	riprap	protects house & road, hard to see	old	pre 1990			mature		20 to 40 m	157.19775975100
SK080A-1	SK080A	LB	hardened bank	none	riprap	protects trailers at Cape Horn area	old	pre 1990	> 2'		mature	riparian zone has houses scattered in it	> 60 m	87.04816062430
SK080A-2	SK080A	RB	hardened bank	none	riprap/rubble	protects house	new	post 1990			mature	concrete slab placed at bottom of bank to protect house, about 70' wide, riparian zone has houses in it	> 60 m	32.30458945140
SK080A-3	SK080A	LB	hardened bank	none	riprap	protects road(?) or old railroad grade	old	pre 1990		sanded in	mature	starts across from Hause Sl	20 to 40 m	930.75856397700
SK080A-4	SK080A	RB	hardened bank	none	riprap/groin	protects house	new	post 1990	< 2'		mature	groin/deflector 20' wide, protects shacks seen at edge of woods	> 60 m	16.78093882830
SK080A-5	SK080A	RB	hardened bank	none	riprap	protects Hwy 20	old	pre 1990	> 2'		immature	old riprap downstream side	5 to 20 m	140.30346904600
SK080C-1	SK080C	RB	hardened bank	none	riprap	protects Hwy 20	old/new	pre 1990/post 1990	> 2'		immature	new rock on east end, old riprap downstream side, ends at bedrock/boulder area	5 to 20 m	420.20975910300
SK080C-2	SK080C	RB	hardened bank	none	riprap/rubble/car bodie	protects houses and road	old	pre 1990			mature	rubble and car bodies scattered in w/ riprap to Lorensen Creek, ends at bedrock/boulder field, cedar(2' dbh)/alder(16"dbh)	> 60 m	985.24274372200
SK080C-3	SK080C	LB	hardened bank	none	riprap	protects houses	old	pre 1990	> 2'		mature	ends across from red house on RB, riparian zone is scattered trees	> 60 m	341.86379751200
SK080C-4	SK080C	LB	hardened bank	none	riprap	protects Sauk-Concrete Rd.	old	pre 1990	> 2'		mature	2 tris enter in this area, ends in bedrock high bank at Dalles bridge	> 60 m	936.44345772300
SK080C-5	SK080C	RB	hardened bank	none	riprap	protects Hwy 20	old	pre 1990	> 2'	1-2' w/ some 6-9"	mature	3-4', grasses/alder(14-16"dbh)/cedar/shrubs	< 5 m	761.54758993800