



Skagit County 1923 Courthouse Windows

- 42 (mostly double hung) original wood windows
- 5 double hung steel windows on back stairwell

- Replacement windows:
 - 26 wood windows
 - 43 vinyl windows (multiple types)
 - 25 brick and glass block “windows”

- **141 total, includes panel above rear door**
 - Based on June 2018 inventory

Courthouse Windows – South Face



Original Wood
Wood Replacement
Vinyl
Brick & Glass Block

Four more windows in the covered entry

Courthouse Windows - Sides




Original Wood

Wood Replacement

Vinyl

Brick & Glass Block

Courthouse Windows – North Face



Original Steel

Original Wood

Wood Replacement

Vinyl

Brick & Glass Block

Three more windows on offset east and west facing walls



Window Material Condition, Surface Preparation, and Paint Requirements

Original Wood Double Hung

- Degraded glazing on several windows
- Wood and paint in decent condition
- Lead tests indicate 11-14%



Replacement Wood Window

- Wood glazing beads used in lieu of clay glazing
- Paint condition is often poor and has exposed wood
- Installation dates unknown, most likely about 2000
- Lead tests show no lead in this paint



Window Material Condition, Surface Preparation, and Paint Requirements

Vinyl Double Hung Window



Vinyl Window (no wood trim)



- Multiple window styles and manufacturers
- Unknown installation dates or use of original frame
- Some require no painting, while others have wood in perimeter framing that requires surface preparation for paint to match window color
- Caulking may be required between brick and window perimeter