980526008

4805260188 9805260188 SURVEY IN THE SOUTHWEST QUARTER OF SECTION 18, TOWNSHIP 34 NORTH, RANGE 4 EAST, W.M. MEMORIAL HIGHWAY TRACTS SKAGIT COUNTY, WASHINGTON 98 MAY 26 P1:19 LEGAL DESCRIPTION: CONTROL FILED \_\_\_ Lots 32 and 33, EXCEPT the South 170.57 feet thereof, and all of Lots 30 and 31, "MEMORIAL HIGHWAY TRACTS", as per Plat recorded in Volume 5 of Plats, Page 35, records of Skagit County. Survey Notes and Procedures This survey was performed by standard field traverse with a 02" electronic total station and complies with the minimum required survey precision of 1:10,000. Corner falls 2.4 west of fence per WAC 130-130-090. Basis of Bearings: Plat bearing on the South line of SE 1/4 of Section 13-34-3. DUNBAR ROAD Survey references: Moore's Garden Plat; Short Plats No. 13-77 and 53-89; ROS Vol. 6, pg. 29. 1''=60' This survey has located existing fence lines and other occupational indicators in accordance with WAC 332-130.Said indicators may present a potential for claims of unwritten title ownership. The legal resolution of any such ownership based upon unwritten title claims has not been resolved by this survey. This survey was performed without the benefit of a current title report. Legal description as shown was provided by the client. This survey does not purport to show any easements, convenats, restrictions and/or agreements 6>54. 6>52. 6>54. of record or otherwise, if any. 62,037 S.F. 1.42 Ac. ROAD LEGEND 67.54. Found as noted herein ● Set 5/8 rebar and cap "Mowrer--21,520" 69.22, *32* 33 NOTE ON PLAT RESOLUTION 36 34 West section line There are numerous errors in the distances shown on \*:37. the Plat. This survey has held the Plat distances on the computed from Plat West lines of Lots 29 and 37 as controlling elements.
Lot lines are parallel to the West section line. Street
P.I. is on West section line and 22.5' NELY of NE line and ROS filed in Vol. 6, 61.50' 71.50' 52.00' 85.00° Surveys, Pg. 29. N 89°52'12"W 137.00 N 89°52'12"W 122.00' Rebar falls 0.63 S. & 0.67 E. of Fence is 0.5' N. NOTE: found disturbed concrete mon. at West 1/4. (Leaning NELY nearly horz.) Falls 0.46' N. & 1.09' E. of MEMORIAL HIGHWAY TRACTS record postion. 30 5 27 Fnd nail in concrete mon. as noted on Plat of Moore's Garden Plat. Mon. is 1612.60 North 1/4 East of SW section Fnd #4 rebar in busted corner and 1.79 concrete mon. North of section line S 89°31'00''E 2629.74' 61.00' 61.00' 61.00' 61.00' 62.55 945.35' 61.00' 1052.25'  $\gg$ S 89°52'12"E 300.00 S 89°52'12"E 367.55' Basis of Bearings 24 Fnd 2" Iron Pipe SW corner 18-34-4 South 1/4 Accepted as orignal Fnd mon. with 3" Fnd plugged 2" Iron Pipe Falls 0.05 North of sec. line Cased at S.I. Brass cap. Cased 0.29 West of Plat. Fnd #5 rebar in 1.5" Iron Pipe 1' South of C/L C/L of road N 89°52'12"W Section corner to 1/4 2664.85' Falls S01°22'56"W 52.64 N 89°51'30" E 2665.48 Plat 120 GRAPHIC SCALE - FEET Located In SW 1/4, Sec. 18, Twn. 34 N., Rng. 4 E. RECORD OF SURVEY AUDITOR'S CERTIFICATE SURVEYOR'S CERTIFICATE MICHAEL MOWRER & ASSOCIATES Filed for record this day of May 1998 at 1. 190. M This map correctly represents a survey made by me or under my FOR PROFESSIONAL SURVEYING SERVICES direction in conformance with the requirements of the Survey Recording In Volume of Surveys at page 50 at the request of DON & PAMELA THORNLOW Don Thornlow In April 1998 229 DIGBY ROAD, MOUNT VERNON, WA. 98274 Act at the request of: Records of Skaglt County, Wa. Mike Mowrer Michael T. Mouren Date: May, 1998 Job No: 98-11 Scale: 1"=60' (360) 424-7898 flount , Lawrence Kouhy Jell Michael T. Mowrer PLS No. 21,520 Drawn by: MTM Chk'd by: MTM Deputy Auditor Sheet 1 of 1 County Auditor