

AUDITORS CERTIFICATE FILED THE REQUEST OF SCHEMMER FOR RECORD NOT

200404270065

<u>수</u> 1.41:37AM

Norma Brunnely
SKAGIT COUNTY AUDITOR

COUNTY, WASHINGTON.

PLAT

LEGAL DESCRIPTION:
LOT 11, PLATE 2, "RANCH SAN RECORDED IN VOLUME 6 OF PL JUAN DEL MAR SUBDIVISION NO. 3" ATS, PAGE 19, RECORDS OF SKAGIT (


BASIS OF BEARINGS:
THE NORTHERLY LINE OF THAT 40 ROADWAY ADJOINING THE SOUTHERLY LINE OF LOTS 8
THROUGH 12 AS SHOWN ON PLAT OF RANCHO SAN JUAN DEL MAR SUBDIVISION NO. 3, PLATE
AS RECORDED IN VOLUME 6 OF PLATS, PAGE 19, RECORDS OF SKAGIT COUNTY, WASHINGTON,
BEARS N 41'E ALSO AS PER SURVEY RECORDED UNDER A.F. NO. 9606050026.

SURVEY NOTES:

THIS SURVEY IS A RETRACEMENT OF A SURVEY DONE IN 1996 (A.F. 9606050026) AND FINDS CONDITIONS ESSENTIALLY THE SAME AS THAT SURVEY (INCLUDING OCCUPATIONAL INDICATORS WHICH ARE NOT SHOWN ON THIS SURVEY) WITH THE FOLLOWING EXCEPTIONS.

A. THE CONCRETE FOUNDATION S BOARDS OF THIS HOUSE ARE APP CONCRETE FOUNDATION CORNERS. APPROXIMATELY 0.2 FEET CLOSER THE PROPERTY LINE THAN I I I I

- ₩. ₩. ₩. HH 1/2" OF BANK REBAR AN AND CAP BETWEEN LOTS 11 AND 12 WAS "PEM LS 25971. NOT FOUND AND WAS REPLACED
- $\dot{\mathbf{c}}$ **EXTRA** MIH THE SAME CAP WAS SET ON LINE 57.36 FEET NORTHWEST OF
- D. THE N MOST WESTERLY REBAR A NEW "PEM LS 2 R AND CAP SET FOR 25971" WAS SET. HH PREVIOUS SURVEY WAS FOUND TUO
- FOUNDATION HAS BEEN BUILT ON LOT 11.



SECTION 10, T. 34 N., R. VICINITY MAP i

FREDERIC SURVEY 13916 SEAWARD ক চ্ট্ৰিট্

04122

い こ カ

ANACORTES, YEOMANS WA 98221



317 SCHEMMER ENGINEERING

ANACORTES,

293

-9006

COMMERCIAL AVENUE, 98221 SUITE (360) 101



a survey made by me under my direction in conformance with the Recording Act. This map co map correctly CERTIFICATE represents

DESIGN DRAWN CHECKI	RT#25971			le Survey	5. a	
	DATE BY APP RI		CHECKED	DRAWN	DESIGNED	
	P 2	ВҮ		PEM	PEM	

		5971		, 0)	, VÐ V
CAD	4/20/04	DATE		CHECKED	DRAWN
FILE		ВҮ		KED	N
: 04		APP	ВҮ	LL	PEM
CAD FILE: 04-122		DATE BY APP REVISIONS			•

Monohon - 26-04

CE

PLOT DATE: