

Return to



200009150146

Skagit County Auditor

9/15/2000 Page 1 of 1 4:10:26PM

### LOW FLOW MITIGATION SUMMARY

Property Owner/Grantor: James & Mollie Lama

Grantee: PUBLIC

Property ID #: P 50956 Assessor's Tax Account #: 360518-0-0001-0408

Legal Description: Sec. 18 Twp. 35 Rng. 6 / Plat Name: \_\_\_\_\_ Lot \_\_\_\_\_ Block \_\_\_\_\_  
(when applicable)

Subject: Aquifer Recharge Mitigation Summary to be recorded with Title.

The following is a mitigation summary as required as a condition of issuance for Permit # BE 00-1166 Pursuant to Skagit County Code 14.06.330 sections (2) & (3) this summary shall be recorded with the title.

In that this development/project is within 1/2 mile of a "low-flow" stream as designated by the Washington State Department of Ecology, I, JAMES & MOLLIE LAMA, the undersigned attest and agree to the following:

1. The total impervious surface of the property is less than and shall remain less than 5% of the total lot area, unless the proposed development/project provides mitigation that will collect runoff from the proposed development/project, will treat that runoff, if necessary to protect groundwater quality and discharge that collected runoff into a groundwater infiltration system on site.
2. No lawn watering will be performed from June 1 to September 30. This condition shall remain in effect until the well is abandoned in accordance with Chapter 173-160 WAC and the property is connected to an approved public water supply or a Hydrogeologist confirms that the water source is from a confined aquifer and there is no continuity with a "low-flow" stream. (Skagit County recommends landscaping with native vegetation as much as possible)

Owner: James & Mollie Lama Date: 9-15-00

On this day personally appeared before me SARA ROBSON known to be the individual described herein and acknowledged to me that they signed the same as the free and voluntary act and deed for the uses and purposes therein mentioned.

Sara Robson, Notary Public in and for the State of Washington,  
residing at Stanwood, Wa. 98292 Date: 9-26-2003

