



200306130030
Skagit County Auditor


6/13/2003 Page 1 of 1 9:48AM

DRINKING WATER SYSTEM STATUS REPORT

I, the undersigned property owner, in making an application for a building permit involving a single-family residence acknowledge that this notice is being signed, notarized and recorded in compliance with Skagit County Code Section 12.48.270 in regards to a drinking water quality parameter that exceeds the maximum contaminant level but is treatable to below the maximum contaminant level.

1. I agree to record this notice with the Skagit County Auditor's Office for the purpose of it being made a part of the record of title.
2. I understand that this notice will appear on any title search or record search, and we have no objection nor will we make claims against Skagit County as a consequence of this recording.
3. The drinking water source for this residential building is located in an area exhibiting relic seawater. The inorganic chemistry taken on January 31, 2003 yielded chloride and conductivity levels exceeding the maximum contaminant level (MCL) for drinking water. The levels noted on the date of sampling were: Chloride 650 (MCL = 250 mg/l) and Conductivity 3020 (MCL =700 u ohms). A sodium level of 273 Mg/l was also detected. While no MCL has been established for sodium, 200 mg/l is the maximum level recommended for Healthy adults. High levels of sodium may cause health problems for infants and people with cardiac, circulatory or renal diseases. The American Heart Association recommends a maximum level of 20 mg/l for individuals needing to reduce their salt intake. This drinking water source will be treated to yield drinking water below the MCL via a Kinetic K-2 reverse-osmosis treatment device installed on the kitchen tap. The Health Officer recommends that property owners exercise caution in the use of this drinking water system by:
 - a. conserving drinking water use where possible by installing low water use fixtures and limiting landscape watering,
 - b. testing for conductivity, chloride and sodium on a regular interval as recommended by the manufacturer or at a minimum annually, and
 - c. providing appropriate maintenance to the treatment unit as directed by the manufacturer.
4. Water systems with filed status reports will not be used for the creation of new lots.
5. Specific drinking water system information for this lot may be on file at the Skagit County Planning and Permit Center.

LEGAL DESCRIPTION: 330622-1-001-0302 22-33-6
 SITE ADDRESS:33511 Bamboo Lane, Mount Vernon, WA
 PARCEL NUMBER: P106766
 ASSESSOR'S ACCOUNT NO:330622-1-001-0302
 OWNER (PRINT NAME) John Tengelin
 MAILING ADDRESS:PO Box 1645 Stanwood, WA 98292
 OWNER (SIGNATURE): John Tengelin



Subscribed and sworn before me this 13TH day of JUNE, 13TH 2003
Notary Public in and for the State of Washington.

Patti J. Chambers Residing at Mount Vernon