Survey 2. the Z ¥ Lake _ Cavanaugh, of the WS _ Skagit 4 of Section County, 25, Washington Twp. 33 Ņ, Rng. Q H ×.×.

200709050034 Skagit County Auditor 9:50AM

Lot 22, Block 6, "LAKE CAVANAUGH SUBDIVISION, DIVISION NO. 1", according to the Plat recorded in Volume 5 of Plats, pages 37 to 43 inclusive, records of Skagit County, Washington.

LEGAL DESCRIPTION:


Survey Notes and Procedures This survey was performed by standard field traverse with a 03" electronic total station and complies with the minimum required survey precision of 1: 5,000 per WAC 130—130—090.

Basis of Bearings: Assumed

Survey References: Subject plat; ros vol. 17, pg. 18;

This survey has accepted the found rebars and pipes as the best evidence of original and retracement surveys. The pipes found for centerline monuments do not appear to be original monumentation. They are shown only to show their relationship to the lot corners.

Fnd 1.25" leaning wiy



DALLATIA TON

CERTIFICATE

ents a survey made by me or under my
with the requirements of the Survey Recording
Bart Robinson In August 2007

PROFESSIONAL SURVEYING

S

ERVICES

(360)

Lane,

Mount Vernon,

₩a.

98274

Scale:

1"=30"

Date:

Sept. 2007

Job No: 07-08

Bart Robinson

Drawn by: cad

Chk'd by: mtm

Sheet 1

of 1

MICHAEL MOWRER

æ

ASSOCIATES

21,520

SURVEYOR'S

CERTIFICATE