


THIS SURVEY IS A REVISION OF THE SURVEY RECORDED ON THE 9TH OF SEPTEMBER, 1939, IN BOOK 19 OF SURVEYS, PAGE 770. THIS REVISION IS DUE TO AN INACCURATE CALCULATION OF THE DOUBLE PROPORTION CORNER FOUND AT THE SOUTHWEST CORNER OF SECTION 27. THIS CORNER WAS MOVED S89-21-07 EAST, 1.98 FEET AND ALL THE DEPENDENT CORNERS WERE MOVED OR RECALCULATED TO REFLECT THAT CHANGE.

REVISION DETAIL:

LEGAL DESCRIPTION:
THE NORTH HALF OF THE NORTHWEST QUARTER OF SECTION 26;
THE NORTH HALF OF THE NORTHWEST QUARTER OF SECTION 27;
AND THE NORTH HALF OF THE NORTHWEST QUARTER OF SECTION
27: ALL IN TOWNSHIP 36 NORTH, RANGE 6 EAST, W.M.

SURVEYOR'S CERTIFICATE

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE SURVEY RECORDING ACT AT THE REQUEST OF PETERSEN LAND SURVEYING.



AUDITOR'S CERTIFICATE

FILED FOR THE RECORD THIS 11 DAY OF
September, 20 04 AT 10:18 am IN BOOK
OF SURVEYS ON PAGE
REQUEST OF SIERRA PACIFIC INDUSTRIES.

J. Yonaguni St.
COUNTY AUDITOR


Deputy
Auditor

AUDITOR'S FILE NO. 200909110056

RECORD OF SURVEY
FOR SIERRA PACIFIC INDUSTRIES
MOUNT VERNON, WASHINGTON

NOTES:
SURVEY PROCEDURE: THIS SURVEY WAS ORIGINALLY PERFORMED IN 1997 USING EDM AND 6 SEC. THEODOLITE - TRAVERSE METHOD EQUIVALENT TO PRECISION CLASS RURAL OF WAC 333-130-090.
GLO. CORNERS: MORE DETAILED INFORMATION REGARDING HISTORY, EVIDENCE AND PERTINATING REFERENCES CAN BE FOUND ON WA. LAND CORNER RECORDS FILED WITH SKAGIT COUNTY AUDITORS.

LEGEND:

-  DENOTES ACCEPTED GLO CONTROLLING CORNER POSITION.
- DENOTES CORNER SET BY THIS SURVEY
- 1/2" REBAR W/PLASTIC CAP LS26303.
- + DENOTES A CALCULATED CORNER
- NO MONUMENT SET.