

TOGETHER WITH the Southerly 13 feet of vacated West 7th Street adjoining thereto

A.K.A. 3 of Record of Survey, A. F. No. 9507290082.

Subjuct to easemnets and restrictions of record

### Exist.

40


8

Cascade Utility and Vehicular Traffic: The North 10' of Lot 5, AF # 86091 Natural Gas: The North 10' of Lot 3 , AF # 8707160047

Puget Power: Puget Power: The North 40' of Lot 5 , AF # 8712160054

July 20 July 20

Puget Power: The North 45' of Lot 5 , AF # 940727008 as recorded,



#### AUDITOR'S ord at the request of FairWeather CERTIFICATE



NTY AUDITOR 3:51PM

# 1"=40 FEET

### Traffic: Over and Across the Southeast Corner of Lot 4, AF # 9507290082, led, AF # 8910250053 Street West Kg. Ca. (E12-1220010) 9

N 69.43.08" E 10.80.00

ped rebar 0.55' Kash of

SURVEYOR'S

NOTES:

I, Bearing Datum: Centerline monumentation of Kansas Street, as shown, on Record of Survey, filed under Auditor's File Number, 9507290082.

2, Basis of Bearing; The Record of Survey, filed under 9507290082,

Auditor's File Number

5. Method of Monument Location was by Field Survey

4, Instrument Utilized: TOPCON GTS 2110 Serial No. LG4302

子

S

69.42.21" W 79.97

N 69.42'21"

W

500.00

102:10

LEGEND

Fd. Original Corners, 9307290082,

L5 6922, AF#

d, original corners,

75.05

80.00

(3)0ch

R

Par # 58631

5 69:42:21

80.00

c

# 1/1981

9/8

5, The Field Survey was conducted January 19 through February 2, 2011.

6, Set or verified the property corners of Thomas J. Lebovsky and Patricia Jane Billinghurst's property on 8th West Place, Parcel No. 58631.

7, Found 1/2" Rebars with Cap, LS 9622, along the North and South lines of Parcels No. 58617, 58618, 58619, 58625, 58652, 58652 and 11981. Corners found were consistent with Records of Surveys filed under Auditor File numbers, 9507290082, 200011090148 and 200505150026

9. This survey was performed to locate the position of the Lot corners of Lot 5, AF # 9507290082 and utility/vehicular easements thereon.

8, Lot corners of Lot 3, Record of Survey AF # 9307290082 were calculated

and/or determined from lot corners found and conform to AF#

9507290082

# with the Survey Recording Act for

II. This survey meet or exceed the standards and quidelines set forth in the "Survey Recording Act" Chapter 58,09 RCW. The final results meets or exceeds the standards contained in WAC 332-130-090.

other than those shown

does not necessary show any or all easements, restrictions and/or reservations which may affect this parcel. FairWeather Survey assumes no responsibility for any encumbrances

10. This survey locates all or portions of the exterior boundary of the described parcel and

12. This drawing is the property of FairWeather Surveying and shall not be

an authorized

agent of FairWeather

Surveyor.

used for any

purpose without the written consent of

### SURVEYOR'S CERTIFICATE

This map correctly represents a survey map made by me or under my direction in conformance oovsky and Patricia Jane Billinghurst

## Nair Weather Surveyor

#### T air Weather Surveyor

Set Mag Nails on Centerline 8th Place Wesi

Set ReBar & Cap (15 No. 19657)

Set Railroad Spike

No.

1419 - 15th Street Anacortes, WA 98221 phones: 360.708.7953 cell 360.293.4787 Office

AUDITOR'S

Geomatic Consultant

INDEXING DATA RANGE

K of SW

the

SECTION 23

TOWNSHIP **35** NORTH EAST