


AUDITORS CERTIFICATE

RECORD OF SURVEY AT THE REQUEST OF DALE K. HERRIGSTAD




AUDITOR *James Lundquist* DEPUTY AUDITOR *DKH*

LEGAL DESCRIPTION

1. THE LEGAL DESCRIPTION FOR THIS SURVEY IS A STATUTORY WARRANTY DEED RECORDED UNDER AUDITOR'S FILE #201106300068, RECORDS OF SKAGIT COUNTY, WASHINGTON.

2. FOUND BOATNAIL, PK NAIL OR NAIL AS NOTED.
3. SET REBAR & RED CAP 27807.
4. EQUIPMENT USED: Pentax 323N Total Station.
5. MONUMENTS TIED ON 08-03-2011.
6. ERROR OF CLOSURE MEETS WASHINGTON STATE SURVEY STANDARDS.
7. SURVEY METHOD: STANDARD FIELD TRAVERSE.
8. BASIS OF BEARINGS: RECORDED SURVEY #200702260229.
9. THIS SURVEY WAS PERFORMED WITHOUT THE BENEFIT OF A CURRENT TITLE REPORT. THIS SURVEY DOES NOT PURPORT TO SHOW ALL EASEMENTS RESTRICTIONS, RESERVATIONS, PROVISIONS, COVENANTS OR CONDITIONS WHICH MAY AFFECT THE PARCELS SHOWN HEREON.
10. THIS IS A BOUNDARY SURVEY ONLY. UTILITIES WERE NOT INVESTIGATED.



Dale K. Herrigstad
12-15-2011

SURVEYOR'S CERTIFICATE

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE SURVEY RECORDING ACT AT THE REQUEST OF ROBERT LUNDQUIST IN AUGUST, 2011.

DALE K. HERRIGSTAD, P.L.S. *Dale K. Herrigstad*
Certificate No. 27807
Date 12-15-2011

SHEET 1 OF 1

RECORD OF SURVEY FOR: ROBERT LUNDQUIST

2320 22ND ST
ANACORTES, WA 98221

SURVEY IN THE SE 1/4 OF SECTION 13,
TOWNSHIP 35 N., RNG. 1 EAST, W.M.
CITY OF ANACORTES, SKAGIT COUNTY,
WASHINGTON

HERRIGSTAD ENGINEERING & SURVEYING

4320 Whistle Lake Road, Anacortes, WA 98221 (360) 299-8804

SITE PLAN
SCALE: 1"=30'

GRAPHIC SCALE

