

\$73.00

Return Address:	9/16/201	3 Page	1 of	2 2:15PM
Drinking Water St Document Title: Report	ystem sta	tus		
Reference Number (if applicable):	<u></u>			
Grantor(s):	ு[்] additional gr	antor name:	s on pag	e
11 Judith Sleian	<u></u>			
2)				
Grantee(s):	[] additional gr	antor name:	on page	e
1) Skagit Co Health	Doot	<u> </u>		
2)				
,				
Abbreviated Legal Description:	[] full legal on p	page(s)		
Lot-115 BL/L	ake Cav	DIVE	5//	3
Assessor Parcel /Tax ID Number:	[_] additional po	admun leark	rs on pag)è

P66890

DRINKING WATER SYSTEM STATUS REPORT

I, the undersigned property owner, in making an application for a building permit involving a single-family residence acknowledge that this notice is being signed, notarized and recorded in compliance with Skagit County Code Section 12.48.270 since the drinking water source is an alternative source (S.C.C. 12.48.250) located in a sensitive area (S.C.C. 12.48.260) and requires filtration and disinfection treatment.

- 1. A agree to record this notice with the Skagit County Auditor's Office for the purpose of it being made a part of the record of title.
- 2. I understand that this notice will appear on any title search or record search, and we have no objection nor will we make claims against Skagit County as a consequence of this recording.
- 3. The drinking water source for this single family residence is a surface water source, Lake Cavanaugh. This withdrawal is allowed by the State Department of Ecology under permit #S1-21192C. The certificate allows a maximum of .02 maximum cubic feet per second. See Washington State Department of Ecology for more information.
- The Health Department requires both continuous filtration and disinfection to ensure that the drinking water is consistent and potable. The owner has chosen the following water quality method: a 75 micron cartridge filter followed by a one micron bag filter followed by an ultraviolet disinfection unit prior to serving the whole house. The Health Officer recommends that property owners exercise caution in the use of this drinking water system. Poor water clarity (turbidity) may indicate that pathogens may be present at times in the drinking water. The Health Department further recommends:
 - having spare system components,
 - b. maintaining an operation and maintenance log,
 - c. testing for turbidity during times of poor water clarity,
 - d. testing for bacteria in your drinking water on a quarterly basis and
 - e. providing appropriate maintenance to the filtration and disinfection units as directed by the manufacturer.
- 5. Properties with water systems with filed status reports will not be used as justification for the creation of new lots. Land divisions require either drilled wells or connections to an approved public system.
- 6. Specific drinking water system information for this lot may be on file at the Skagit County Department of Health or in the water files at the Skagit County Planning and Development Services.

SITE ADDRESS: 33158 WEST SHORE DRIVE, MOUNT VERNON, WA 98274

lith On

PARCEL	P66890	
ASSESSOR'S ACCT #	3939-001-115-0000	
LEGAL DESCRIPTION	LAKE CAV. SUB DIV 3	
	LOT 115 BLK 1	

OWNER(S): JUDITH ANNE SLEIGHT & EDWARD F RUNDLE

OWNER (SIGNATURE):

Subscribed and sworn to me this ____

_ day of __\

, 2013.

Notary Public in and for the State of Washington.

Residing at_

Renton

Skagit County Auditor 9/16/2013 Page \$73.00 2 of 2 2:15PM