


AUDITOR'S CERTIFICATE

201310300092

FILED FOR RECORD AT THE REQUEST OF HARMSEN & ASSOCIATES, INC.

Skagit County Auditor \$138.00
10/30/2013 Page 1 of 1 2:18PM

10




- DENOTES 1/2" REBAR WITH #14L 27927 CAP BET THIS SURVEY
- ⊗ DENOTES FOUND 4" X 4" CONCRETE MONUMENT WITH 2-1/4" BRASS DISK WITH PUNCH IN CASING, HELD AS PLAT MONUMENT
- ⊙ DENOTES FOUND 2" DOWED BRASS DISK WITH PUNCH IN CONCRETE AT SURFACE, HELD AS PLAT MONUMENT
- ⊖ DENOTES FOUND 5/8" REBAR WITH "NEWMAN RLS 4908" CAP
- DENOTES FOUND "PK" NAIL
- (M) DENOTES MEASURED DISTANCE AND BEARING
- (R1) DENOTES DISTANCE OF RECORD AS DEPICTED ON THAT SURVEY RECORDED UNDER SAGINAW COUNTY AUDITORS' FILE NO. 9560270063
- (F2) DENOTES DISTANCE OF RECORD AS DEPICTED ON THAT SURVEY RECORDED UNDER SAGINAW COUNTY AUDITORS' FILE NO. 877715

DENOTES FENCE AS DESCRIBED

1. BASIS OF REPAIRS: N-0118 OF E ALONG THE CENTERLINE OF "D" AVENUE AS DOCUMENTED AND SHOWN HEREON AND BY THIS SURVEY RECORDED UNDER SKAGIT COUNTY AUDITOR'S FILE NO. 9606270063.
2. THIS SURVEY WAS ACCOMPLISHED BY FIELD PARCELS WITH A 3-SECOND ELECTRONIC DIGITAL TOTAL STATION.
3. THIS SURVEY MEETS OR EXCEEDS THE ACCURACY STANDARDS SPECIFIED BY WAC 352-330-090.
4. THE LEGAL DESCRIPTION REATED HEREON WAS PROVIDED BY STATUTORY WARRANTY DEED RECORDED UNDER SKAGIT COUNTY AUDITOR'S FILE NO. 9607070094.
5. THIS SURVEY DOES NOT purport to show all easements or encumbrances, recorded or unrecorded, that may affect the depicted properties.
6. ENCUMBRANCES ARE DEPICTED HEREON IN ACCORDANCE WITH THE REQUIREMENTS OF WAC 352-330-050. THIS SURVEY DOES NOT RESOLVE ISSUES OF ENCUMBRANCE OR OCCUPATION.

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE SURVEY RECORDING ACT AT THE REQUEST OF CLAUDIA E. TRIGVE, IN OCTOBER, 2013.

[illegible]

SECTION 25 TOWNSHIP 35N RANGE 1E WM

SCALE: 1" = 30' DRAWN BY: JAH DOT: 07/2013	PROJECT: 13-229 F/B: MM-94 SHEET: 1 OF 1
---	---