Return Address:	
	201409300107 Skagit County Auditor \$73.00 9/30/2014 Page 1 of 2 3:19PM
	Water System Status Report
Reference Number (if applicable):	Ladditional granter names on page
Grantor(s): 3 CO++ A. Lea	[_] additional grantor names on page
2)	
Grantee(s):	[] additional grantor names on page
1) <u>Public</u> 2)	
Abbreviated Legal Description:	[_] full legal on page(s)
L+98 BIK 1 L	ake cav. sub oil 3
Assessor Parcel /Tax ID Number:	[_] additional parcel numbers on page

·

DRINKING WATER SYSTEM STATUS REPORT

If the undersigned property owner, in making an application for a building permit involving a single-family residence acknowledge that this notice is being signed, notarized and recorded in compliance with Skagit County Code Section 12.48.270 since the drinking water source is an alternative source (S.C.C. 12.48.250) located in a sensitive area (S.C.C. 12.48.260) and requires filtration and disinfection treatment.

- I agree to record this notice with the Skagit County Auditor's Office for the purpose of it being made a part of the record of title.
- 2. Junderstand that this notice will appear on any title search or record search, and we have no objection nor will we make claims against Skagit County as a consequence of this recording.
- 3. The drinking water source for this single family residence is a surface water source, Lake Cavanaugh. This withdrawal is allowed by the State Department of Ecology under permit #S1-27253C. This permit allows a maximum of 150 gallons per day and in-house supply. This water right provides adequate quantities of water for one residential connection only. This alternative source cannot serve proce connections or an accessory dwelling unit.
- 4. The Health Department requires both continuous filtration and disinfection to ensure that the drinking water is consistent and potable. The owner has chosen the following water quality method: Bruner F-10-AG Series filter w/auto backwash, followed by a Pentek ECP5-BB 5 micron cartridge filter, then to ultraviolet disinfection (UV Pure Technologies Inc. Model Cactus X-12 Crossfire) unit prior to serving the whole house. The Health Officer recommends that property owners exercise caution in the use of this drinking water system. Poor water clarity (turbidity) may indicate that pathogens may be present at times in the drinking water. The Health Department further recommends:
 - having spare system components,
 - b. maintaining an operation and maintenance log,
 - c. testing for turbidity during times of poor water clarity,
 - d. testing for bacteria in your drinking water on a quarterly basis and
 - e. providing appropriate maintenance to the filtration and disinfection units as directed by the manufacturer.
- 5. Properties with water systems with filed status reports will *not* be used as justification for the creation of new tots. Land divisions require either drilled wells or connections to an approved public system.
- 6. Specific drinking water system information for this lot may be on file at the Skagit County Department of Health or in the water files at the Skagit County Planning and Development Services.

SITE ADDRESS: 33082 DEER PARK LANE, MOUNT VERNON, WA 98274

PARCEL	P66874
ASSESSOR'S ACCT #	3939-001-098-0001
LEGAL DESCRIPTION	LAKE CAV. SUB DIV 3
	LOT 98 BLK 1

OWNER(S): Scott A. Lemke	
OWNER for full	(SIGNATURE)
Subscribed and sworn to me thisday or Notary Public in and for the State of Washington.	
at Car Hwayr	ng Summing DA



Skagit County Auditor 9/30/2014 Page

\$73.00

2 of 2 3:19PM