



6

AUDITOR'S CERTIFICATE

Filed for record at the request of Fair Weather Surveyor.



## SURVEYOR'S NOTES:

1. Bearing Datum: A.F. 's  $\pm 201508120002$  and  $\pm 9201510064$ 

- 2. Basis of Bearing; A.F. #201508120002
- 3. Method of Monument Location was by Field Survey.
- 4. Instrument Utilized: TOPCON GTS 2110 Serial No. LG4502

N 01°52'04" E 295.65

K Avenue

- 5. The Field Survey was conducted March, 2015, Corners set March 17, 2015,
- 6, Set and or verified the property comers of George M. and Patricia L. Hatfield property at 1408–15th Street, Parcel No., 55755,
- 7. Found property corners of three (3) ROS's as noted; Auditor's File Nos, 201508120002, 9201510064 and 200208080100,
- 8. Survey held street monumentation and Record of Surveys corners as found.
- 9. This survey was performed to locate the boundaries of Lot 5, Block 118, Plat of
- 10. This survey locates all or portions of the exterior boundary of the described parcel and does not necessarily show any or all easements, restrictions and or reservations which may affect this parcel. FairWeather Survey assumes no responsibility for any encumbrances other than those shown.
- Recording Act<sup>11</sup> Chapter 58.09 RCW. The final results meet or exceed the standards 11. This survey meets or exceeds the standards and quidelines set forth in the "Survey contained in WAC 352-150-090.
- purpose without the written consent of an authorized agent of FairWeather Surveyor. 12. This drawing is the property of FairWeather Surveying and shall not be used for any



24 May 2015



## **FairWeather**

Surveyor

1419 - 15th Street Anacortes, WA 98221 phones: 360.708.7953 cell 360.293.4787 Office

Geomatic Consultant

AUDITOR'S INDEXING DATA RANGE **1** EAST

K the NE of SECTION 24 TOWNSHIP

35

NORTH