BOUNDARY RESOLUTION: I FOUND THREE CENTERLINE MONUMENTS AT THE LOCATIONS SHOWN. I USED THEM TO FIND ORIGINAL LOT CORNERS AT THE CORNERS NUMBERED 1-4, 6-7, & 9.

THE MEASURED DELTA OF THE CURVE BETWEEN THE MONUMENTS FOUND AT NUMBERS 1 & 6 WAS FOUND TO BE WITHIN 3 SECONDS OF THE PLATTED VALUE. THE CORNERS BETWEEN THESE MONUMENTS (THE SOUTHWEST AND SOUTHEAST CORNERS OF LOT 26) WERE SET ACCORDING TO SINGLE PROPORTION.

THE CORNER NUMBERED 5 WAS SET BY SINGLE PROPORTION BETWEEN THE FOUND MONUMENTS AT 4 & 6.

ALONG CAPE HORN DRIVE, MONUMENTS WERE FOUND AT NUMBERS 7 & 9. THE LOCATION OF NUMBER 9 MATCHED THE PLATTED LOCATION BY 0.08' UNDER MY BASIS OF BEARING. I SET THE MONUMENT AT NO. 8 ACCORDING TO THE PLATTED DIMENSIONS.

IN GOVERNMENT LOTS 6 & 8, IN THE NORTHWEST QUARTER OF THE SOUTHEAST QUARTER, AND ALSO IN THE SOUTHWEST QUARTER OF THE NORTHEAST QUARTER, OF SECTION 12, TWP. 35 N., RGE. 7 E., W.M.,

FILED FOR RECORD AT SURVEYING, PLLC

THE REQUEST OF ZITKOVICH LAND

AUDITOR'S CERTIFICATE


Skagit ©2bnty A 6/28/2016 Page

SKAGIT COUNT

MONUMENTS AT POINT NUMBERS 1,3 & 1/2 INCH IRON PIPES. 9 ARE

MONUMENTS AT POINT NUMBERS 2,4,6 & 7 ARE 1/2 INCH IRON PIPES GUARDED BY STEEL FENCE POSTS EXCEPT FOR NUMBER 6 WHICH IS GUARDED BY A 2" PVC SET SOLIDLY IN THE

ALL MONUMENTS DEPICTED ON THIS MAP WERE FOUND ON 6/21/2016 & 6/22/2016.



N 87

10° E

30,

SURVEYOR'S CERTIFICATE

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE THE REQUIREMENTS OF THE SURVEY RECORDING ACT AT THE REQUEST OF THE SURVEY RECORDING ACT AT THE REQUEST OF THE SURVEY BOTTOM OF THE SURVEY RECORDING ACT AT THE REQUEST OF THE SURVEY RECORDING ACT AT THE SURVEY R

STEPHEN ANTHONY ZITKOVICH DATE

CERTIFICATE NUMBER 46904

à

2016



SURVEY OF LOTS 26, 27 & 28, BLOCK E, OF CAPE HORN ON THE SKAGIT

IN GOVERNMENT LOTS 6 & 8, IN THE NORTHWEST QUARTER OF THE SOUTHEAST QUARTER, AND ALSO IN THE SOUTHWEST QUARTER OF THE NORTHEAST QUARTER OF SECTION 12, TWP. 35 N., RGE. 7 E., W.M., SKAGIT COUNTY, WASHINGTON

OMAR for ROS. B CEJA MORENO A BARRERA ARCINIEGA &

LEGAL DESCRIPTION

DEPUT

DESCRIBED IN QUITCLAIM DEEDS FILED UNDER AUDITOR'S FILE NUMBERS 201501120128 AND 201605270003

- SET A REBAR AND CAP STAMPED: ZITKOVICH LS 46904
- FOUND 1/2 INCH IRON PIPE, ACCEPTED AS ORIGINAL PLAT MONUMENT
- FOUND CONCRETE MONUMENT WITH LEAD PLUG AND COPPER TACK 6/21/2016
- = DIMENSION RECORDED ON THE PLAT
- = MEASURED DIMENSION ON 6/21/2016-6/22/2016

- BASIS OF BEARING: S 73°21'30' E ALONG THE CORD BETWEEN THE SHOWN CENTERLINE MONUMENTS, ACCORDING TO THE PLAT OF CAPE HORN ON THE
- THIS SURVEY WAS PERFORMED BY A STANDARD FIELD TRAVERSE USING A LEICA TCRP 1203 (3 SECOND) TOTAL STATION. THIS SURVEY MEETS OR EXCEEDS THE ACCURACY REQUIREMENTS SPECIFIED IN W.A.C. CH. 332-130-090.
- THIS IS BOUNDARY SURVEY ONLY, NEITHER UTILITIES NOR TOPOGRAPHY WERE SURVEYED.
- THIS SURVEY WAS PERFORMED WITHOUT THE BENEFIT OF A TITLE REPORT, IT DOES NOT PURPORT TO SHOW ALL EASEMENTS, RESTRICTIONS, RESERVATIONS, PROVISIONS, COVENANTS OR CONDITIONS WHICH MAY AFFECT THE PARCELS
- THERE IS A SCRIVENER'S ERROR ON SHEET 5 OF THE PLAT. THE DELTA FOR THE MARGIN OF THE RIGHT OF WAY FOR LOTS 24-27 IS 8° 15', NOT THE 8° 51' AS SHOWN ON THE PLAT.
- THIS SURVEY HAS DEPICTED OCCUPATIONAL INDICATORS IN ACCORDANCE WITH W.A.C. 332-130. THESE OCCUPATIONAL INDICATORS MAY A POTENTIAL FOR CLAIMS OF UNWRITTEN TITLE OWNERSHIP. NO CLAIM IS MADE BY THIS SURVEY AS TO ANY UNWRITTEN RIGHTS CONCERNING THESE ITEMS.

ZITKOVICH LAND SURVEYING, PLLC

44906 CONCRETE ROAD CONCRETE, WA 98237

(360) 391-3494

CHECKED BY: SAZ, FIELD BOOK: 28 DATE OF FIELD WORK: 6-21-2016 & 6-22-2016 SCALE: 1"=40"