

## AUDITOR'S CERTIFICATE

Filed for the record at the request of LeGro & Associates, LLC.



LEGAL DESCRIPTION

CASCADE RIVER PARK NO. 1," as per plat recorded in Valurie 8 of Plats, pages 55 through 59, inclusive, under Audito's File No. 639857, records of Skagit County, Washington.

Situate in the County of Skagit, State of Washington.

## NOTES

- Legal Description for this survey has been based upon that Statutory Warranty Deed from Tommy J. Morrison, as his separate property, to Joe Black & Laurie Black, h&w by that instrument dated August 26, 2016 and recorded September 15, 2016 under Auditor's File No. 201609150020, records of Skagit County, Washington.
- For additional survey information refer to the Plat of Cascade River Park No. 1 as per plat recorded in Vol. 8 of Plats, at pages 55—59 under Auditor's File No. 639857, records of Skagit County, Washington. Refer also to notes on Record of Surveys recorded under Auditor's File No's. 200311040109 and 200509090094.
- 3. Basis of Bearing The line between the Northerly corner common to Lots 62 and 63 and the Northerly corner common to Lots 58 and 59 as being N 20°28'00" E based upon existing found lot corners as denoted.
- Assumed

- 6. Distances shown are in feet and decimals of a foot.
- This survey has been performed without the benefit of a current title report and is subject to any Easements, Conditions, Covenants, Restrictions, Reservations or other instruments of record.

## **EGEND**

- Length Steel Rebar
- Set 5/8" Diam. x 18" Length Steel Rebow/ Yellow Plastic Cap Imprinted: "LEGRO 37532"
- Found/Set Refers to the Date of the Survey unless Otherwise Noted.

Sheet 1 ᅌ

얶 SURVEY

**PROPERTY** RIVER PARK 4 SURVE **⊗**.M. N E

GOV'T. LOT 1 IN THE SE 1/2 SEC. 15, T. 35 N., R. 11 E., SKAGIT COUNTY, WASHINGTON