



NOTES
 * This survey was conducted by means of a closed traverse between existing corners and/or prior control, using a Leica TS06+ TOTAL STATION (least read 0.5"). The relative accuracy of this control exceeds 0.0000.
 ** Each new BT was measured to the center, referenced by a stake on the right side center and contains scribbling and a reference tag.



SURVEY REFERENCES
 1) 1982 SURVEY BY F. HAMMON, LS-17667, BK 5 PGS 86-92
 2) 1982 SURVEY BY F. HAMMON, LS-12716, BK 4 PGS 51

SECTION CORN
 Fd. 2-1/2" aluminum pipe w/3" stamped USFS aluminum cap (see SR-1)

FD REFERENCES
 -23" NEMLOCK W/SNIKE & HEALED FACE.
 -N2+30 W-31.5" REF. POST EAST-4.0'
 -USFS ALUMINUM REF. POST, EAST-4.4'
 -50.5' ALUMINUM REF. POST, SOUTH-4.4'

NEW REFERENCES
 -F. ALDER, BARK SCRIBED (134NRT 3348 TL)
 -S. HEMLOCK, SCRIBED (134NRT 3348 TL)
 -53.9'E-12.9'
 -6" W. PIN, SCRIBED (134NRT 3348 TL)
 -ADP-E-16.3'



BASIS OF BEARING
 (N89°59'41" W - 2623.94' SR-1)
 N 89°59'41" W - 2623.50'

USFS SNOQUALMIE N.F.

WEYERHAEUSER CO.

BASIS OF BEARING
 (S69°28'46"E SR-2)
 S 69°25'11" E - 593.96'



1/4 CORN
 Fd. 2-1/2" aluminum pipe w/3" stamped USFS aluminum cap in mound of stone (see SR-5-12)

FD REFERENCES
 -42" W. PIN W/SNIKE & HEALED FACE.
 -NS9°E-17.3'
 -9" HEMLOCK STAKE, 6" TALL W/YS SCRIBED
 -31" HEMLOCK W/OVEN FACE, S40°W-7.3'
 -USFS ALUMINUM REF. POST, EAST-1.0'

NEW REFERENCES
 -4" CEDAR SCRIBED (1/8 BT) S03°E-12.9'

A DEPENDENT RESURVEY
 for Weyerhaeuser Co. of the
 North line of SECTION 35, T34N RTE. W.M.
 lying West of USFS Road 17
 as situated within
 SKAGIT COUNTY, WASHINGTON

LEGEND
 * = A corner FOUND or SET during a previous survey.
 Δ = A corner FOUND or SET during a previous survey.
 A = A glass boundary line post found within 1.0' of line unless noted otherwise.
 () = A Bearing and/or Distance of record
 USFS = US Dept. of Agriculture, Forest Service
 A line marked during this survey with 1/2" x 6" white fiber glass rods, pointed bases and tagging

USFS
 ROAD-17
 Fd. USFS aluminum boundary post, held for a point on line (see SR-2)

SURVEYOR'S CERTIFICATE
 This map correctly represents a survey made by me or under my direction, in conformance with the requirements of The Survey Recording Act of 1971, February 19, 1971, RCW 65A.02.010

AUDITOR'S CERTIFICATE
 I, John A. ... Auditor of Skagit County, do hereby certify that the foregoing is a true and correct copy of the original as filed for record this 3rd day of August, 2018.
 County Auditor
 201808030002

AUDITOR'S CERTIFICATE
 I, John A. ... Auditor of Skagit County, do hereby certify that the foregoing is a true and correct copy of the original as filed for record this 3rd day of August, 2018.
 County Auditor
 201808030002

HAMPSTUR CORPORATION

Controlled by: CH

Checked by: CH

Drawn by: TIG

Completion date: 7/10/2018

Field Book no.: P5-605

Drawing No.: 18-631/DWG

HAMPSTUR JOB no.: 18-631

HAMPSTUR SHEET no.: 1 of 1

P.O. Box 283
 Kelso, Washington 98626
 Phone: (360) 423-8166