


In Government Lot 11, in the Northeast Quarter of the Southeast Quarter of Section 27, Twp. 33 N., Rge. 6 E., W.M., Skagit

RECORD OF SURVEY



BASIS OF BEARING: S 85° 02' 30" E PER THE PLAT FROM THE FOUND CENTERLINE MONUMENT OPPOSITE LOT 102 TO THE FOUND CENTERLINE MONUMENT OPPOSITE LOT 97.

- OTHER ADJONING AND NEARBY SURVEYS HAVE BEEN RECORDED UNDER SKAGIT COUNTY AUDITORYS NOS. 8903280042, 9106130036, 9309280100, 9806240008, 200207180103 & 200509300011. NO ORIGINAL MONUMENTS WERE FOUND AT THE CORNERS OF LOTIOS, BLOCK 1. THE CENTERLINE STREET MONUMENTS CLOSEST TO LOTS 106 AND 67 ARE NOT RELIABLE. USING THE MONUMENTS OPPOSITE LOTS 10 AND 97 PRODUCES AGREEMEN WITH THE SURVEYS OF LOTS 101-105 & 109 RECORDED UNDER ADDITORS FILE NOS. 2201240012, 2010140014, 201015 101-105 & 100 RECORDED UNDER ADDITORS FILE NOS. 2201240015
- THIS IS A BOUNDARY SURVEY ONLY NEITHER UTILITIES NOR TOPOGRAPHY ARE
- THIS SURVEY WAS PERFORMED USING A LEICA TCRP 1203 TOTAL STATION, IT WAS PERFORMED BY MEAUS OF A STANDARD FIELD TRAVERSE AND MEETS OR EXCEEDS THE ACCURACY REQUIREMENTS OF W.A.C. CH. 332-130-090.
- THIS IS A SURVEY OF THE BOUNDARIES, IT DOES NOT PURPORT TO SHOW AL EASEMENTS, SETBACKS, RESTRICTIONS, RESERVATIONS PROVISIONS, COVENANTS OR CONDITIONS WHICH MAY AFFECT THE PARCELS SHOWN.
- RESTRICTIONS AND COVENANTS ON THE FACE OF THE PLAT OF LAKE CAVANAUGH INCLUDE: NO BUILDING SHALL BE CONSTRUCTED CLOSER THAN 10 FEET TO ANY LOT BOUNDARY.
- THIS SURVEY HAS DEPICTED OCCUPATIONAL INDICATORS (CONCETTE DRIVEWAY) IN ACCORDANCE WITH W.A.C. CH.332-130, THESE OCCUPATIONAL INDICATORS MAY INDICATE A POTENTIAL FOR CLAINS OF UNWRITTEN TITLE OWNERSHIP. THE LEGAL RESOLUTION OF OWNERSHIP BASED UPON UNWRITTEN TITLE CLAIMS HAS NOT BEEN RESOLUTION OF THIS SURVEY.
- WHERE ORIGINAL MONUMENTS HAVE BEEN FOUND, THE MEASUREMENTS TO THEM AND BETWEEN THEM ARE INDICATED BY DIMENSIONS WITHIN A RECTANGLE
- ORIGINAL MONUMENTS WERE FOUND AT FOUR CORNERS OF LOT 67, BLOCK 3. MEASUREMENTS TO ADJACENT MONUMENTS WERE SHOWN FOR THE PURPOSES OF RETRACEMENT AND RECOVERY.
- FOUND 1.14 OUTSIDE DIAMETER TRON PINCH PIPE WITHIN A CONCRETE CYLINDER. THIS PIPE IS RUSTED ALMOST IN TWO AT THE SURPACE. I REPLACED THE PIPE BY SETTING A REBAR AND CAP AT THE SAME LOCATION OF THE PINCH PIPE AND TIED THE PIPE TO THE REBAR.
- FOUND 1.14 OUTSIDE DIAMETER IRON PINCH PIPE. THIS PIPE IS RUSTED AUMOST IN TWO AT THE SURFACE. AT THE POSITION OF THE PIPE I SET A REBAR AND CAP AND LEFT THE PIPE ADJACENT TO IT.
- THE SHORELANDS OF THE SECOND CLASS, AS DESCRIBED IN STATUTORY WARRANTY DEED, PER AFN 201808170096, HAVE NOT BEEN SURVEYED BY THIS SURVEY.

- SET REBAR AND CAP STAMPED: ZITKOVICH, LS 46904, THE DATE IS 12-19-2018 UNLESS OTHERWISE NOTED
- O FOUND REBAR & CAP: LS 12716, 7-21-2014 SET MAG NAIL AND WASHER: 46904, 7-30-2014
- FOUND 1 1/2 IN IRON PIPE, JUDGED ORIGINAL MONUMENT, THE DATE IS 12-27-2018 UNLESS NOTED OTHERWISE MEASURED DIMENSIONS BETWEEN ORIGINAL PLAT MONUMENTS

--- EDGE OF PAVEMENT

Zitkovich Land Surveying, PLLC

CONCRETE, WA 98237

F FIELD WORK: 12-19-2018 TO 12-27-2018) BY: SAZ, JANUARY 3, 2019	
2-27-2018 PAGE 2 OF 2	2019 SCALE 1" = 30 FT	
2	= 30 FT	

CHECKED DATES OF

for Getaway Holdings, LLC