


Legal
Lot 9, Cedar Hills, No. 3, according to the Plat thereof, Recorded in Volume 9 of PLATS, Page 36, Auditor's File No. 700555,
TOGETHER WITH The Southeastern 30 feet abutting thereof, A.F. No. 201802270058, Records of Shaght County, Washington State



SURVEYOR'S CERTIFICATE
This map correctly represents a survey map made by me or under my direction in conformance with the Survey Recording Act for Daniel J. and Catherine L. Daman
Mukam, Vernon, Washington.
Daniel J. Daman
Registered Professional Land Surveyor, U.S. No. 19637
Date: 27 Nov 19

Fair Weather Surveyor 1419 - 15th Street Anacortes, WA 98221 Phone: 360.708.9555 Office (cell)			
AUDITOR'S INDEXING DATA			
SW of the SW	SECTION 28	TOWNSHIP 34 NORTH	RANGE 4 EAST

Fd. Rebar & Cap, LeGro

Cor. fell on Lg. Rock (Did not set)

LEGEND

- Fd. Original Corners as noted.
- Fd. Property Corners as noted
- Set Rebar & Cap (L.S. No. 19637).
- + Property Corners as noted

1. The field survey was conducted March, 2016. Corners set April, 2016.
2. Set and / or verified the property corners of Daniel J. and Catherine L. Daman property at 25948 Crosby Drive, Mukam, Vernon, Parcel No. 045940 and amended by A.F. No. 201802270058.
3. Found property corners of the Plat of Cedar Hills, No. 3.
4. Survey held in de nomination as found.
5. This survey was performed to locate and establish the SW and SE 1/4 Corners of Lot 9 and Lot 9 (amended) by A.F. No. 201802270058 (4/29/18)
6. This survey locates all or portions of the corner boundary of the described parcel and does not necessarily show any or all easements, restrictions and/or reservations which may affect this parcel. Fair Weather Surveyor assumes no responsibility for any encroachments other than those shown.
7. This survey meets or exceeds the standards and guidelines set forth in the "Survey Recording Act" Chapter 58.09 RCW. The field results meet or exceed the standards contained in WAC 592-150-090.
8. This drawing is the property of Fair Weather Surveyor and shall not be used for any purpose without the written consent of an authorized agent of Fair Weather Surveyor.

SCALE: 1"=20 FEET
0 10 20 40



Crosby Drive

Lot 8

Lot 9

House

Deck

Drain Field

Fd. TP

SURVEYOR'S NOTES:

1. Plat of Cedar Hills No. 3, A.F. No. 700555
2. Basis of Bearing: Plat of Cedar Hills No. 3, A.F. No. 700555
3. Method of Monument location was by Field Survey.
4. Instrument Utilized: TOPCON GTS 2110 Serial No. L4H302.
5. The legal descriptions for this survey are a personal representative's deeds recorded under Auditor's File Numbers 700555 and 201802270058.
6. The Field Survey was conducted March, 2016. Corners set April, 2016.
7. Set and / or verified the property corners of Daniel J. and Catherine L. Daman property at 25948 Crosby Drive, Mukam, Vernon, Parcel No. 045940 and amended by A.F. No. 201802270058.
8. Found property corners of the Plat of Cedar Hills, No. 3.
9. Survey held in de nomination as found.
10. This survey was performed to locate and establish the SW and SE 1/4 Corners of Lot 9 and Lot 9 (amended) by A.F. No. 201802270058 (4/29/18)
11. This survey locates all or portions of the corner boundary of the described parcel and does not necessarily show any or all easements, restrictions and/or reservations which may affect this parcel. Fair Weather Surveyor assumes no responsibility for any encroachments other than those shown.
12. This survey meets or exceeds the standards and guidelines set forth in the "Survey Recording Act" Chapter 58.09 RCW. The field results meet or exceed the standards contained in WAC 592-150-090.
13. This drawing is the property of Fair Weather Surveyor and shall not be used for any purpose without the written consent of an authorized agent of Fair Weather Surveyor.

AUDITOR'S CERTIFICATE
Filed for record this 27 day of Nov, 2019 at 11:59 a.m. under Auditor's File No. 201911270100 at the request of Fair Weather Surveyor.
Daniel J. Daman
Shaght County Auditor
Dan J. Daman
Deputy Auditor