
202004300138 64/39/220 62:12 PPI Pages: 1 of 1 Fees: \$187.59



Amendment to Record of Survey filed under Skagit County Auditor's File No. 201906170169

LEGEND

at the request of Zitkovich Land Surveying, PLLC

AUDITOR'S CERTIFICATE


- Found concrete monument with lead plug and brass tack on 6/5/2019
- Found 3/4" outside diameter iron pipe on 6/5/2019
- Set rebar and cap on 6/6/2019 stamped: Zitkovich, LS 46904
- Recorded plat distance
- M = Measured distance

Legal Description

Lots 4 and 5, Block B, Division 1, "CAPE HORN ON THE SKAGIT, Skagit County, washington", as per the plat recorded in Volume 8 of Plats, pages 92-97 inclusive, records of Skagit County, Washington.

Lane, Concrete, Washington

Source of legal description is Sheriff's Deed filed under Auditor's File No. 201004230058, records of Skagit County, Washington.





Skagit County Auditor

Soudry Texpins

NOTES

Also commonly known as 41317 North Shore

- Basis of Bearing: N 57°08' E between the shown centerline monuments, according to the plat of CAPE HORN ON THE SKAGIT.
- 2 All monuments where either found or set on June 5th or 6th, 2019.
- 3 This survey was performed by a standard field traverse using a Leica TCRP 1203 (3 second) total station. This specified in W.A.C. Ch. 332-130-090. survey meets or exceeds the accuracy requirements

4 This is boundary survey only, neither utilities

nor topography were surveyed

6 This survey has shown occupational indicators according to W.A.C. 332-130-050 1.f.vii These indicators may represent a potential for claims of numritten title. Legal ownership based upon unwritten title has not been resolved by this survey. which may affect the parcels shown.

5 This survey was performed without the benefit of a title report, it does not purport to show all easements, restrictions, reservations, provisions, covenants or conditions

The plat description makes a call to the Skagit River. That boundary (the line of ordinary high water) was not determined by this survey. I have shown a staking line as platted in 1965, the current top of bank, and an approximate location of the Ordinary High Water Mark at the date of the survey.

The area below the staking line is subject to flooding. I have set monuments on the lines in locations that are relatively safe from destruction. Also, it appears that there has been considerable accretion to these lots since the time of the plat in 1965.

Zitkovich Land Surveying, CONCRETE, WA 98237 , PLLC

CHECKED BY: SAZ, April 30, 2020 SCALE:

DATES OF FIELD WORK: 6-5-2019 TO 6-6-2019 (360) 391-3494 SCALE: 1"=40"

Certificate Number 46904

Surveyor's Certificate

This map correctly represents a survey made by me or under my direction in conformance with the the requirements of the Survey Recording Act at the request of Lisa, Holmquist, in June, 2019

John Mahay Alband 4-30-2020 Stephen Anthony Zitkovich