

**Subject:** Skagit County wq sampling in the Samish, 10/26/11

Normal ambient samples were obtained on a flat hydrograph with no rainfall in the preceeding 24 hr on 10/26. Results (below) show mostly low numbers, starting to creep up a little at some of the drainage ditches. There was a documented large population of gulls in the Edison Pump Station drainage.

10/26/2011

<b>Location</b>	<b>Site Number</b>	<b>Fecal Coliform (cfu/100 mL)</b>	<b>Duplicate sample</b>
Samish River at Hwy 9	11	13	
Parsons Creek at mouth	PAR	33	
Samish River above Parsons Creek	SAMPAR	4.5	
Skarrup Creek at Double Creek Ln	SKAR	23	
Swede Creek at Grip Rd	8	79	130
Samish River at F&S Grade Rd	SAMFS	23	
Friday Creek at Prairie Rd	6	33	
Thomas Creek at F&S Grade Rd	4	22	
Thomas Creek at Hwy 99	3	70	
Samish River at Thomas Rd	32	23	33
Alice Bay Pump Station	33	46	
Edison Slough at School	36	21	
Edison Pump Station	37	170	
North Edison Pump Station	38	130	
Colony Creek at Colony Road	39	49	

Rick Haley  
Water Quality Analyst  
Skagit County Public Works  
Water Resources Management  
1800 Continental Place  
Mt. Vernon, WA 98273  
[rickh@co.skagit.wa.us](mailto:rickh@co.skagit.wa.us)  
360-419-3424  
360-336-9400