

Samples were taken during flat hydrograph after several days of little or no rainfall. Mid-Samish PIC stations not sampled due to lack of rainfall. Results reflect those conditions, very low to non-detect fecal coliform in a number of locations. Further samples were taken in response to rain events on 12/8 and 12/9, results will be reported when available.

Location	Site Number	FC, cfu/100 mL	Duplicate
Thomas Creek at Hwy 99	3	<2	
Thomas Creek at F&S Grade Road	4	23	
Friday Creek at Prairie Rd	6	13	
Swede Creek at Grip Rd	8	13	
Samish River at Hwy 9	11	<2	<2
Samish River at Thomas Rd	32	13	22
Alice Bay Pump Station	33	30	170
Edison Slough at School	36	13	
Edison Pump Station	37	13	
North Edison Pump Station	38	130	
Colony Creek at Colony Rd	39	17	

Rick Haley
 Water Quality Analyst
 Skagit County Public Works
 Water Resources Management
 1800 Continental Place
 Mt. Vernon, WA 98273
rickh@co.skagit.wa.us
 360-419-3424 (desk)
 360-336-9400 (Public Works receptionist)